

CRESTS OF FLAKE RIDGES
REMOVED FOR STRAIGHTNESS

TOP TO BE REMOVED

DIRECTION OF
BLOW




Fig 5




Fig 6




Fig 7